# Lab 03

Complex Parts: Shells and Ribs

Dr. Mohammad A Gharaibeh

3D Modeling with complex parts

200

60

30

Depth = 200
Rip thickness = 20

50

30

60°

10

60°

300

Homework

- Create the following part using CREO software and the presented dimensions

- Your revolve should be at 360 degrees